Work Order I March-21-14 7:52:3.			*115	26	*							Page 1	-
Item ID: D356 Revision ID:	66-1		Accept	*N	300	140	100)*	Setup	Start		S1*	
Item Name: Gask	et Fwd & Aft		v s							Stop	*N!	S2*	
Start Date: 3/21	/14 Start Qty: 20.00	*203	1/2	Cu	st Item II) :							
Required Date: 3/25	/14 Req'd Qty: 20.00	*26	* 40°	Cu	stomer:								
Reference:		//"	·										
	ocess Plan:	Date:	Tooling:		Da	te:			Run	Start Stop	*NI	⊋ 1*	
QC	:	_ Date:	SPC (Y/N):		Da	te:				ыор	*NI	ヲク*	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	T	ool ID	Tool #	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Revision Nbr												-
D3566	Rev C				ı								
100			0.00								,		_
100	FLOW WATER JET							45			mm/E	14/04	6
Waterjet	Memo		0.00										,
FLOW CNC Waterjet	1-Cut as pe Deburr if n		v: [)3566_ Prog Rev:	2-							l		
110	QC2- Inspect parts off r	nachine FAI/FAIB	0.00 AS					i No			•		
110			W. W.	_				100			m	2 14/0	4/
QC	Memo		0.00									-,	• ,
Quality Control													
120	QC8- Inspect parts - sec	rand check	0.00 07]								
1 <i>2</i> 00	QOO- Inspect parts - sec	ond enter	4.89					45					
QC QC	Memo		11411										

Quality Control

·											
Work Ordo		15261		*115	526	1*					Page 2
Item ID: Revision ID: Item Name:	D3566-1 Gasket Fwd	& Aft		Accept	*N	ററ	040	100)* s	Setup Star	
Start Date: Required Date: Reference:	3/21/14 3/25/14	Start Qty: 20.00 Req'd Qty: 20.00	*20* *20*			st Item I stomer:	D:	·		a .	
Approvals:		Plan:	Date:	Tooling: SPC (Y/N):		<u> </u>	nte:		F	Run Star Stoj	"INH I"
Sequence ID/ Work Center II 130 *130*	D	Operation Description Identify as per dwg & Sto	ck Location: [7 ⁻ -00]	Set Up/ Run Hours 0.00	T	ool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Insp. Number Stamp
Packaging Packaging		Memo		0.00					A 10	7	

0.00

0.00

QC21- Final Inspection - Work Order Release

Memo

140

140

Quality Control

#1404-2 H404-02

March-21-14 7:52:30 AM

Work Order ID: 115261

115261

Parent Item:

D3566-1

D3566-1

Parent Item Name:

Gasket Fwd & Aft

Start Date: 3/21/14

Required Date: 3/25/14

Start Qty: 20.00

Required Qty: 20.00

Comments:

IPP Rev:A

New Issue 07-03-08 ec

IPP Rev:B

Added Drain Holes 07-07-09 JLM

IPP Rev:C

C As per Rev C 07-09-09 JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MNEO60S.063		Purchased	No		100	sf	1,120.100	0.911	21			
*MNFO60								**	25579	Ex	m 1	4/04/01

NEOPRENE SHEET 0.063

DART AEROSPACE LTD	Work Order:	115201
Description: Gasket	Part Number:	D3566-1
Inspection Dwg: D3566 Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

				Γ	T	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.10	+/-0.030	3.10	/		v 5tm.05	
18.00	+/-0.030	1800	/		TJm-07	
12.10	+/-0.030	12.10			T "	-
2.43	+/-0.030	2,43	\checkmark		V "	
6.00	+/-0.030	6.00			7 "	·
1.40	+/-0.030	1.48	V	·	V	
0.30	+/-0.030	. 30	/		" V	
0.30	+/-0.030	.30	V		V	
0.063	+/-0.010	.063	\checkmark		V "	
Ø0.188	+0.005/-0.001	0.186	V		1-	
	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
_						

		\$		DAS		
Measured by:	mm	EZ	Audited by:	27) 9- 4 9	Prototype Approval:	N/A
Date:	14/04	/01	Date:	14/4/)	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.03.14	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM 1.4	
С	07.09.26	Dwg Rev updated	KJ/EC/DD	E

The state of the s				
		~		
				;
			•	
				:
				•
			·	
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				



